

Operating Instructions Art.No. 30.5007
Pro digital thermo-hygrometer

Features:

- * electronic multi-purpose thermo-hygrometer for temperature and humidity measurement
- * memory for the highest and lowest values
- * ON/OFF button
- * °C/°F-switch

Specification

Measuring range: temperature: -20 °C to +50 °C

humidity: 20 % to 90 %

Resolution: temperature: 0.1°C

humidity: 1 %

Battery: 1,5 V LR44 button cell

Attention: Used batteries have to be put in the specially reserved collecting receptacles.

Use:

- * Open the battery compartment and remove the battery safety strip or insert the battery. Close the battery cover. The unit is now ready to use. The display shows the current temperature and humidity.
- * The temperature unit can be changed from °C to °F by use of the C/F-button.
- * Press the MAX/MIN button and the highest temperature and humidity is displayed since the last reset (upward arrow). Press the MAX/MIN button again, the display shows the lowest values since the last reset (downward arrow).
- * To reset the MAX/MIN-memory to the present values press the CLEAR-button, while the MAX/MIN-values are displayed (- --). To go back to the present values, press the MAX/MIN button once more.

Maintenance:

- * Do not expose the instrument to extreme temperatures, vibration or shock
- * Clean it with a soft damp cloth. Do not use solvents or scouring agents.
- * Please do not try to repair the unit. Contact the original point of purchase. Please change the battery before complaining. No guarantee if the instrument is handled or opened improperly .